Notification of Hazardous Waste Site

United States Environmental Protection Agency Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

NJS 000 001 187

1	Person Required to Notify:	Name Merck & Co., Inc.		
	enter the name and address of the person or organization required to notify.	Street 126 East Lincoln Avenue		
		City Rahway State N.J. Zip Code 07065		
3	Site Location:	MERCK + CO., INC.		
	Enter the common name (if known) and actual location of the site.	Name of Site _ Rahway Plant		
	actual location of the site.	Street 126 East Lincoln Avenue		
	NJD001317064	County Union State N.J. Zip Code 07065 Environmental		
2	Person to Contact:	Name (Last, First and Title) Puchalski, Tom Control Manag		
	Enter the name, title (if applicable), and business telephone number of the person	Phone (201) 574-5361		
	to contact regarding information submitted on this form.			
)	Dates of Waste Handling:			
	Enter the years that you estimate waste treatment, storage, or disposal began and	From (Year) Unknown To (Year) 1979		
	ended at the site.			
 E	Waste Type: Choose the option you pr	efer to complete		
	Option I: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site. Option 2: This option is available to persons familiar with Resource Conservation and Recovery Act (RCRA) Section 3 regulations (40 CFR Part 261).			
		of Waste: i X in the appropriate EPA has assigned a four-digit number to each hazardous velisted in the regulations under Section 3001 of RCRA. Enter appropriate four-digit number in the boxes provided. A cope the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the		
	1. Organics 1. D M 2. Vinorganics 2. D C	located.		
	2. by thorganics 2. □ Cf 3. ☑ Solvents 3. □ Te	extiles extiles		
٦	4. ☐ Pesticides 4. ☐ Fe			
		aper/Printing eather Tanning		
		on/Steel Foundry		
	•	hemical, General		
	-	lating/Polishing		
		Nilitary/Ammunition		
		lectrical Conductors		
		ransformers		
		Itility Companies		
		anitary/Refuse		
-		hotofinish		
	16. □ L	ab/Hospital _		
		Inknown Other (Specify)		
	A			

Lorm Approved ФМВ No. 2000 0138

	Notification of Hazardous Waste Site	Side Two			
F	Waste Quantity	Facility Type	Total Facility Waste Amount		
	Place an X in the appropriate boxes to indicate the facility types found at the site.	1 □ Piles .	cubic feet Not Known		
	In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site	Land Treatment Landfill	gallons		
4		4. 🗆 Tanks	Total Facility Area		
J	using cubic feet or gallons.	5. 🗆 Impoundment	square feet NOT Known		
,	In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.	6. ☐ Underground Injection 7. ☐ Drums, Above Ground			
1		8 Drums Relow Ground	acres		
		9. Other (Specify) ST	oill Areas)		
G	Known, Suspected or Likely Releases to the Environment:				
	Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment. Suspected Likely None (3)				
-	Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so				
H	Sketch Map of Site Location: (Optiona	1).			
	Sketch a map showing streets, highways. Refer to maps that were submitted with the routes or other prominent landmarks near				
	the site. Place an X on the map to indicate		ation and Recovery Act (RCRA		
£.,	the site location. Draw an arrow showing the direction north. You may substitute a	Part A permit app	olication for site NJD001317		
, in	publishing map showing the site location.	•			
,					
		•			
1		A Comment			
•					
	Description of Site: (Optional)				
•	Describe the history and present	For location deta	ails, refer to maps that wer		
	conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such		art A RCRA permit application		
		for site NJD00131			
	information as how waste was disposed and where the waste came from. Provide	· - -	cturing operations at Rahway		
	any other information or comments which may help describe the site conditions.	All areas are cov			
	may help describe the site conditions.		e landfill poses any risk to		
		human health or t	the environment.		
		Spill areas consi	st of localized on site de-		
			e resulted from tank leakage		
		and sewer line de			
			these deposits pose any ris		
_			or the environment.		
J	Signature and Title:				
	The person or authorized representative	Name Merck & Co., Ir	Owner, Present		
	(such as plant managers, superintendents, trustees or attorneys) of persons required	Street 126 East Lincol	n Ave Owner, Past		
	to notify must sign the form and provide a mailing address (if different than address		Li Transporter		
	in item A). For other persons providing notification, the signature is optional.	City Rahway State	NJ Zip Code 07065 Operator, Present Operator, Past		
	Check the boxes which best describe the	() // ()	☐ Other		
	relationship to the site of the person required to notify. If you are not required	Signature Seel HILL	- 18 B B		
	to notify check "Other"	Joseph H. Donah	iue -		


ahway Plant Manager

[FR Doc. 81–11500 Filed 4–14–81; 8:45 am] BILLING CODE 6560–29–C



MERCK CHEMICAL MANUFACTURING DIVISION

MERCK & CO., INC. • P.O. BOX 2000, RAHWAY, N.J. 07065



REGISTER INAIL

U.S. Environmental Protection Agency Region II Sites Notification New York, New York 10007

Registered Mail - Return Receipt Requested

R-1047.35-G

